

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
1	BRS	L1	69735	beam same (coupling or connection)	USPAT; EPO; JPO; DERWENT	2003/02/20 09:59			0
2	BRS	L2	1275	beam with hollow same (coupling or connection)	USPAT; EPO; JPO; DERWENT	2003/02/20 09:57			0
3	BRS	L3	20	beam with hollow same (coupling or connection) same weld	USPAT; EPO; JPO; DERWENT	2003/02/20 09:58			0
4	BRS	L4	896	beam same (coupling or connection) same (overlap or overlapped)	USPAT; EPO; JPO; DERWENT	2003/02/20 09:59			0
5	BRS	L5	15	beam same (coupling or connection) same (overlap or overlapped) same weld	USPAT; EPO; JPO; DERWENT	2003/02/20 10:01			0
6	BRS	L6	3	beam same "overlapped connection"	USPAT; EPO; JPO; DERWENT	2003/02/20 10:01			0